User:

Wednesday, 05/11/2008 1:10:18 PM

Linda Lacelle

Process Sheet

Customer

: CC-DAR01 Dart Aerospace Ltd.

Job Number **Estimate Number** : 43217

P.O. Number

: 10804

This Issue

: 05/11/2008

S.O. No. :

: NC

First Issue

: 00015

: 05/11/2008 Type

: SMALL /MED FAB

Part Number

Drawing Name

: D3562042

: D412-630-034

Drawing Number

: DISASSEMBLE

Project Number

Drawing Revision Material

: 12/11/2008 **Due Date**

Qty:

1 Um: Each

Written By

Prsht Rev.

Checked & Approved By

Comment

Previous Run

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

REMOVE FROM STOCK:

1 X D412-630-034 B_4099 \$

DISASSEMBLE TO SHIP STEP WELDMENT ONLY IDENTIFY PARTS BEING RETURNED TO STOCK:



Date: User: Wednesday, 05/11/2008 1:10:18 PM Linda Lacelle **Process Sheet** Customer: CC-DAR01 Dart Aerospace Ltd. Drawing Name: D412-630-034 Job Number: 43217 Part Number: D3562042 Job Number: Seq. #: Machine Or Operation: **Description:** D412630034 2.0 Heli Access Step RH Folding Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Heli Access Step RH Folding PACKAGING 1 PACKAGING RESOURCE #1 3.0 Comment: PACKAGING RESOURCE #1 RETURN ITEMS TO STOCK, : REPACKAGE D3562-042 STEP ONLY, USING NEW B/N 43217 ADJUST ACCPAC: 4.0 QC21 FINAL INSPECTION/W/O RELEASE Comment: FINAL INSPECTION/W/O RELEASE Job Completion